•	•	Approved	l For Release	2006/01/12/	VOIN-KOPS	39BQ0551	R0008002	and an arrangement of the second seco	name to the second age of the	Account of the second
DATE :	1733Z 5	ост 59		SECF	* E T	2 3	MAT	5 6	ORS KE	25X
TO TOURECTOR										
FROM :		25X1A					gantausen förster sammaksplaner estekning i förertiller elikte Programming förste för side till distrationer i side karry i det til Landsprogramming side förste entiden side förste i side karry i det til	en variable de la companya de la com		Final Company
ACTION:	N: DFD (1,2,3,4,5,6,7,8,9,Ø)						ROUTINE			
INFO :	S/C (11)					Village meddink framse pli tig, glawn emyddin regnal i	Canadigation research secretary in the state of		Application of the property of the control of the c	Action is common only common only of the common of the com
	SAD							IN Ø873	35	11 c 6 c c c c c c c c c c c c c c c c c
Control of the same of the sam	TCR: 17	33Z 5 OCT	59	Northead Committee of Michigan and State of Stat	man	po 11. Bibler s religios com apognocima distribus (inspendance de la relación de la glacifica medicione des distribus despresarios	а ульта түүдү жанас астышуулан арауучун ада 2 - Ибу буюлдансуу жана тутар дайдай, 5 Иб		na, waki ishi sanci sengagan saliki sa manga ingkasantah Malaksi ing s	
10		25X1A	INFO				CITE	Ø	5 <b>84</b>	25X1A

FOLLOWING MALFUNCTIONS NOTED DURING POST-FLIGHT OF MISSION 4139:

- A. CHANNEL 13, 76 MCS IMPROVED VIDEO LOST. THIS DUE TO FAILURE OF 100B, 50-100 MCS ATTENUATOR.
- B. "B" RECORDER, PILOTS COMMENT FAILED APPROX 1 1/2 HOURS AFTER SIGHTING OF TARGET. CAPSTAN MOTOR FAILED.

END OF MESSAGE

CV.

